



Agricultural Engineering Update



Structures & Environment



Soil & Water



Energy



Safety



Crop Processing



Power & Machinery

AEU-34

GRAIN DRYING & STORAGE - QUICK REFERENCE CHART

Doug G. Overhults & Sam G. McNeill
Extension Agricultural Engineers

OPERATING CONDITIONS (CORN)

Drying System	Suggested Maximum Moisture Content, %	Suggested Airflow CFM/BU	Drying Air Temp., °F	Relevant Fact Sheets
Natural air/Lo temp (full bin drying)	(Sept) 16% (Nov) 18%	1-2	2-10° above outside	AEN-22,23
Layer drying (no stirring)	22	2-5	10-20° above outside	AEN-56
(with stirring)	22	2-5	15-30° above outside	AEN-56,62
Batch-in-bin (4ft/no stirring)	28	8-12	120-140°	AEN-57
(6ft/stirred)	28	7-10	120-160°	AEN-57,62
In-bin continuous flow	28	3-12	120-160°	AEN-62,63
Automatic batch or continuous flow	28	75-150	180-240°	AEN-61

Dryeration - Dry corn to between 16% and 18% with high speed dryer; transfer to tempering bin and hold for 4-10 hours; then aerate at 1/2-1 cfm/BU to remove last 2-3 points of moisture. Move dry cool grain to storage bin.

Dryeration with in-bin cooling - Move hot corn from dryer into storage bin. Cool immediately with 1 cfm/BU to remove 1/2-1 point of moisture.

Combination drying - Dry corn to between 16% and 18% with high speed dryer and move hot to another drying bin. Finish drying with natural air or low temperature system.

(continued)

RECOMMENDED STORAGE MOISTURE CONTENTS FOR KENTUCKY (AEN-45)

	<u>Through Winter</u> (Nov. - March)	<u>Through</u> <u>summer</u>
Corn	15.0	13.0
Soybeans	13.0	11.0
Milo	14.0	13.5
Wheat	13.5	12.5

AERATION & COOLING (AEN-45)

- All grain must be cooled after drying.
- Aeration is recommended for all storages greater than 1000 bushels & storage longer than 30 days.
- Grain should be cooled when it is 15-20 degrees warmer than the monthly average temperature.

APPROXIMATE COOLING TIMES

<u>Cfm per bushel</u>	<u>Hours of Fan</u> <u>Operation per cooling</u>	<u>Operating Procedure</u>
1	15-20	Operate fans when temperature is in desired range and humidity is less than 70%.
3/4	20-25	
1/2	30-40	
1/4	60-80	
-----	-----	-----
1/5	75-100	Fans may be operated continuously until grain is cool.
1/10	150-200	

If no airflow data is available, a rough estimate is 1000 cfm per fan horsepower (i.e. a 5 hp fan will provide about 5000 cfm)

RECOMMENDED GRAIN TEMPERATURES (AEN-45)

<u>MONTH</u>	<u>GRAIN TEMPERATURE</u>
September	65° - 70°
October	55° - 60°
November	45° - 50°
Dec - Feb	35° - 40°

Operating fans at temperatures below 25° is not recommended except in emergency situations.

9/87